



POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION

REGION

SITE NUMBER

6

OKO 5061

NOTE The initial identification of a potential site or incident should not be interpreted as a finding of illegal activity or confirmation that an actual health or environmental threat exists. All identified sites will be assessed under the EPA's Hazardous Waste Site Enforcement and Response System to determine if a hazardous waste problem actually exists.

A SITE NAME

TURNER BROTHERS' PIPE YARD

B STREET (or other identifier)

4725 N BOULEVARD

C CITY

EDMOND

D STATE

OK

E ZIP CODE

73034

F COUNTY NAME

OKLAHOMA

G OWNER/OPERATOR (if known)

1 NAME GARY RITZKY, SAFETY MANAGER

2 TELEPHONE NUMBER

TURNER BROTHERS TRUCKING Co, INC

405-682-6900

H TYPE OF OWNERSHIP (if known)

☐ 1 FEDERAL☐ 2 STATE☐ 3 COUNTY☐ 4 MUNICIPAL☒ 5 PRIVATE☐ 6 UNKNOWN

I SITE DESCRIPTION

IN SECT 11, T14N, R3W IM
LARGE OILFIELD SERVICE PIPEYARD AND TRUCKYARD ACTIVITIES
INCLUDE PIPE WASHING, PIPE CLEANING, TRUCK CLEANING
SOIL SURFACE IS MAINTAINED BARE (VOID OF VEGETATION)
INCLUDED A LANDFILL AREA, BURNED AND COVERED
SITE COVERS MOST OF E $\frac{1}{2}$ OF E $\frac{1}{2}$ OF SECT 11

J HOW IDENTIFIED (i.e., citizen's complaint, OSHA citations, etc.)

CITIZEN'S COMPLAINT TO OKLA WATER RESOURCES BOARD

K DATE IDENTIFIED

(mo day & yr)
6-28-82

L SUMMARY OF POTENTIAL OR KNOWN PROBLEM

UNPERMITTED LANDFILL, UNPERMITTED DISPOSAL OF HAZARDOUS WASTES, INDUSTRIAL WASTES, AND OILFIELD WASTES. FAILURE TO CONTROL SEDIMENT LOSSES IN RUNOFF. METALS, TOXICS, AND PESTICIDES FOUND IN SAMPLES ON AND OFF SITE. PROBABLE CONTAMINATION OF PONDS ON NEIGHBORING PROPERTY. POSSIBLE GROUNDWATER CONTAMINATION. POSSIBLE DISPOSAL OF PCB-CONTAMINATED EQUIPMENT IN LANDFILL.

SUPERFUND FILE

9798543



JUN 10 1992

REORGANIZED

3012 Site

M PREPARER INFORMATION

1 NAME

JOHN N. ICE HYDROLOGIST, OSDH

2 TELEPHONE NUMBER

405-271-5338

3 DATE (mo day & yr)

10-19-84